



NUMBER: 18-007-10

GROUP: Vehicle Performance

DATE: March 20, 2010

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THE wiTECH DIAGNOSTIC APPLICATION IS THE PREFERRED METHOD FOR FLASHING ECUs. HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING “HELP” THEN “HELP CONTENTS” AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE LEVEL MUST BE AT RELEASE 10.02 OR HIGHER TO PERFORM THIS PROCEDURE.

StarMOBILE DESKTOP CLIENT or StarSCAN MAY ALSO BE USED TO PERFORM THIS PROCEDURE.

SUBJECT:

Flash: MIL Illumination P0730 And/Or P0731 And Fuel Economy Improvement

OVERVIEW:

This bulletin involves selectively erasing and reprogramming both the Powertrain Control Module (PCM) and Transmission Control Module (TCM) with new software.

MODELS:

2008	(WK)	Grand Cherokee
2008	(WH)	Grand Cherokee (International Markets)
2008	(XK)	Commander

NOTE: This bulletin applies to all vehicles equipped with a 3.7L engine (Sales code EKG) and a NAG1 transmission (Sales code DGJ).

SYMPTOM/CONDITION:

The customer may experience a MIL illumination (4WD or AWD models only) with one or both of the following Diagnostic Trouble Codes (DTC) when accelerating on slick road surface and experiencing momentary wheel slippage:

1. P0730 - Incorrect Gear Ratio
2. P0731 - Gear Ratio Error in 1st

This Software also gives a fuel economy improvement for all WK/WH/XK vehicles. The software now has a interactive fuel shut off strategy and the optimization of TCM shift and torque converter clutch lock up/unlock schedules. This improvement could be as much as +0.5 MPG in city driving conditions. Not all vehicles will realize a improvement due to driving habits and optional equipment that may have been installed on the vehicle.



Stick with the Specialists™

DIAGNOSIS:

Using a Scan Tool (wiTECH™) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all engine and transmission systems are functioning as designed. If DTC's are present other than the one's listed above record them on the repair order and repair as necessary before proceeding further with this bulletin.

If the above condition is present, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	04275086AB	Label, Authorized Modification

REPAIR PROCEDURE:

NOTE: The flash update is a combination flash that will update both the PCM and TCM controllers.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM/TCM with the latest software. Follow the detailed service procedures available in DealerCONNECT/TechCONNECT, Refer To Group 8 - Electrical > Electronic Control Modules - Service Information > Module - Powertrain Control > Standard Procedures > PCM/ECM Programming - Gas. **After PCM reprogramming, the following must be performed:**
 - a. Clear any DTC's that may have been set in other modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow the tech to clear them.
2. Type the necessary information on the "Authorized Modification Label" and attach it near the VECI label.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
18-19-06-92	Module, Powertrain Control and Transmission Control (PCM/TCM) - Reprogram (C)	0.2 Hrs.
International Related Operation		
18-00-00-WT	StarSCAN/StarMOBILE (International) (C)	AT

FAILURE CODE:

FM	Flash Module
----	--------------