



NUMBER: 08-024-08

GROUP: Electrical

DATE: August 15, 2008

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler LLC.

SUBJECT:

MYGIG Radio Hard Drive Recovery/Update Disc

OVERVIEW:

This bulletin involves updating the MYGIG radio software with the software update DVD.

MODELS:

2008	(HB)	Durango
2008	(HG)	Aspen
2007 - 2008	(JK)	Wrangler
2007 - 2008	(JS)	Sebring/Avenger/Sebring Convertible
2007 - 2008	(KA)	Nitro
2008	(KK)	Liberty
2008	(LE)	300C/300C Touring (International Markets)
2008	(LX)	300/Magnum/Charger
2008	(ND)	Dakota
2008	(RT)	Town & Country/Grand Caravan
2008	(WH)	Grand Cherokee (International Markets)
2008	(WK)	Grand Cherokee
2008	(XH)	Commander (International Markets)
2008	(XK)	Commander

NOTE: This bulletin applies to the above listed vehicles equipped with MYGIG radios (sales code RER, REW or REP)

SYMPTOM/CONDITION:

Customers may experience a condition where the hard drive becomes corrupt. If corrupt, the radio will have all 3 of the following conditions:

- a. The radio does not go past the "Navigation is being activated" screen.
- b. Music on the hard drive cannot be accessed.
- c. Capacity of the hard drive shows 0.

NOTE: To access the hard disc drive capacity:

1. Press the Menu Hard Key
2. Press System Setup
3. Press Manage HDD
4. Press Display Available Space on HDD

PARTS REQUIRED:

Qty.	Part No.	Description
1	68054781AA	RER/REW MYGIG Radio Software Update Disc
1	68054782AA	REP MYGIG Radio Software Update Disc

DIAGNOSIS:

If the MYGIG radio has all 3 of the Symptom/Conditions above, perform the Repair Procedure. If the radio does not have all 3 symptoms, perform additional diagnostics outlined in DealerConnect.

NOTE: Updating the MYGIG radio with this software does not affect the photos or music previously stored in the radio by the customer.

REPAIR PROCEDURE:

1. Insert vehicle key and turn to ACC. position.
2. Turn radio ON.
3. Insert software update DVD into radio.
4. Radio will read the disc and prompt user to perform software update.

NOTE: Radio may take 1 - 2 minutes to prompt for software update. In the following step there are 2 portions to the software update. Radio will reset before and after each portion.

5. If radio software is older than the update DVD software, i.e.; "Update from 8.044 to 9.717", select "Yes".

NOTE: Once software update has begun, do not power off vehicle and do NOT touch the radio.

6. Once software update is complete, radio will return to the normal user screen. Wait for radio to re-read DVD and prompts user to update software again. Software levels shown should now be identical, i.e.; Update from 9.717 to 9.717". Select "No" to return to user screen.
7. Eject software update DVD.
8. Turn vehicle off and allow CAN bus to go to sleep (approx. 1 min).
9. Turn key to ON.
10. Select Menu hard key on radio.
11. Select "System Setup" on the display
12. Select "System Information" the display
13. Confirm software display shows the correct level.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
08-60-02-98	Software Update MYGIG Radio (B)	0.4Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------